

January 2023

If there is a 10mm hole in the top of the rudder blade, like this:



Close the hole with Sikaflex 221, or similar.

It's because the rudder is made a few days ago, and it need to breathe a week more.

Med venlig hilsen
JEFA Marine A/S

Jan Faurschou